This Page Is Inserted by IFW Operations and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.






Figure 3








Figure 4. 0228sd67.5






Figure 5. Cross-section of 0410S67.5









Figure 6. Close-up of 0410S67.5



Figure 7





Forward Flow Bubble Point in 60/40 IPA/H2O PVDF Membrane - 90 mm Disc




Figure 8

7/14






Figure 9






Figure 10. Cross section of 0508lam






Figure 11. Close up of Figure 10



Forward Flow Bubble Point in 60/40 IPA/H₂O Bobcat Casting Trial - Sample 206




Figure 12






Figure 13. Cross-section of membrane # 0103



Forward Flow Bubble Point in 60/40 IPA/H₂O

Nylon Membrane Sample 103




Figure 14



14/14




Figure 15. Order of dope application: slot C, B, A